



2018-19 water fixture test results and mitigation for Yukon schools

The chart states the number of fixtures:

- identified for replacement or repair; and
- the mitigation work that took place.

Specific values obtained during testing are available for each school in the linked PDF documents.

School	Number of water fixtures we identified for replacement	Upgrade work completed	Results report
Christ the King Elementary	3	3 fixtures replaced; extra tests show clean results.	Report 1 Report 2 Test results following the replacement of fixtures.
Del Van Gorder, Faro	16	8 fixtures and isolation valves replaced with February and July 2019 testing. 5 fixtures removed. 2 water bottle fill stations installed.	Report
Eliza Van Bibber, Pelly Crossing	26 (including 2 drinking water fountains; 4 kitchen sinks)	All fixtures replaced; extra tests show clean results at the majority of the new fixtures; 3 classroom fixtures and 1 drinking fountain remain designated as non-drinking sources until further notice.	Report 1 Report 2 A 2nd round of testing was completed to get flushed samples. Report 3 Test results following the replacement of fixtures.
Émilie Tremblay	2	3 water bottle fill stations installed.	Report
F.H. Collins Secondary	0	None required	Report
Gadzoosdaa Student Residence	0	None required	Report
Golden Horn Elementary	5	Repairs at all fixtures now complete; extra tests show clean results.	Report 1 Report 2 Test results following the replacement of fixtures. Report 3 Test results following extra repairs.
Ghùch Tlà Community, Carcross	16 (including 4 kitchen sinks)	All fixtures replaced; extra tests show clean results at the majority of fixtures; 5-bathroom fixtures will remain designated as non-drinking sources until further notice.	Report 1 Report 2 A 2nd round of tests was done at this school to ensure testing validity. Report 3 Test results following the replacement of fixtures.

Grey Mountain Primary	1 (including 1 drinking water fountain)	Drinking fountain replaced; extra tests show clean results.	Report 1 Report 2 Test results following the replacement of fixtures.
Hidden Valley Elementary	1 (including 1 drinking fountain)	1 water bottle fill station installed.	Report
Holy Family Elementary	1 (including 1 drinking fountain)	1 water bottle fill station installed.	Report
Jack Hulland Elementary	13	All mitigation work complete; extra tests show clean results.	Report 1 Report 2 A 2nd round of testing was completed to get flushed samples. Test results following the replacement of fixtures: Report 3 Report 4
Johnson Elementary, Watson Lake	1	Fixture replaced; extra tests show clean results.	Report 1 Report 2 Test results following the replacement of fixtures.
J.V. Clark, Mayo	42 (including 3 kitchen sinks; 4 drinking fountains)	20 fixtures and isolation valves replaced with February and August 2019 testing. 11 fixtures removed. 2 water bottle fill stations installed, and 2 Elkay fountains installed.	Report
Khatinas.àxh, Teslin	6 (including 1 kitchen sink)	Repairs of all fixtures now complete; extra tests show clean results.	Report 1 Report 2 Test results following the replacement of fixtures. Report 3 Test results following extra repairs.
Kluane Lake, Destruction Bay	0	None required.	Report
Nelnah Bessie John, Beaver Creek	1 (including 1 drinking water fountain)	Drinking fountain replaced; extra tests show clean results.	Report 1 Report 2 Test results following the replacement of fixtures.
Porter Creek Secondary	20	All fixtures replaced; extra tests show clean results at the majority of the new fixtures; 5 classroom sinks will remain designated as non-drinking sources until further notice.	Report 1 Report 2 A 2nd round of testing was completed to get flushed samples. Report 3 Test results following the replacement of fixtures.

Robert Service, Dawson City	34 (including 1 drinking water fountain; 1 kitchen sink)	Repairs at all fixtures now complete; extra tests show clean results.	Report 1 Report 2 A 2nd round of testing was completed to get flushed samples. Report 3 Test results following the replacement of fixtures. Report 4 Test results following extra repairs.
Ross River School	0	None required	Report
Selkirk Elementary	7	7 fixtures replaced; extra tests show clean results.	Report 1 Report 2 Test results following the replacement of fixtures
St. Elias Community, Haines Junction	1	1 fixture replaced; extra testing being scheduled.	Report
Takhini Elementary	2	2 fixtures replaced; extra tests show clean results.	Report 1 Report 2 Test results following the replacement of fixtures.
Tantalus School, Carmacks	0	None required	Report
Teen Parent Centre	0	None required	Report
St. Francis Catholic Secondary	16	Repairs at all fixtures now complete; 2 bathroom fixtures will be permanently labelled as non-drinking sources.	Report 1 Report 2 A 2nd round of testing was completed to get flushed samples. Report 3 Test results following the replacement of fixtures. Report 4 Test results following extra repairs.
Watson Lake Secondary	46 (3 kitchen sinks)	3 fixtures and isolation valves replaced with July 2019 and February 2020 testing. 1 water bottle fill station installed.	Report
Whitehorse Elementary	3	3 fixtures replaced; extra tests show clean results.	Report 1 Report 2 Test results following the replacement of fixtures.
Wood Street Centre	7 (including 1 drinking fountain)	7 fixtures replaced; extra tests show clean results.	Report 1 Report 2 Test results following the completion of mitigation work. Report 3 Test results following the replacement of fixtures.